



## TABELA CONVERSÃO MESH → MICRAS

MESH	MICRONS	INCHES	MILIMETROS
1 in.	25400	1.00	25.4
7/8 in.	22600	0.875	22.6
3/4 in.	19000	0.750	19.0
5/8 in.	16000	0.625	16.0
0.530 in.	13500	0.530	13.5
1/2 in.	12700	0.500	12.7
7/16 in.	11200	0.438	11.2
3/8 in.	9510	0.375	9.51
5/16 in.	8000	0.312	8.00
3	6730	0.265	6.73
1/4 in.	6350	0.250	6.35
3 1/2	5660	0.223	5.66
4	4760	0.187	4.76
5	4000	0.157	4
6	3360	0.132	3.36
7	2830	0.111	2.83
8	2380	0.0937	2.38
10	2000	0.0787	2
12	1680	0.0661	1.68
14	1410	0.0555	1.41
16	1190	0.0469	1.19
18	1000	0.0394	1
20	841	0.0331	0.841
25	707	0.028	0.707
30	595	0.0232	0.595
35	500	0.0197	0.5
40	400	0.0165	0.4
45	354	0.0138	0.354
50	297	0.0117	0.297
60	250	0.0098	0.25
70	210	0.0083	0.21
80	177	0.007	0.177
100	149	0.0059	0.149
120	125	0.0049	0.125
140	105	0.0041	0.105
170	88	0.0035	0.088
200	74	0.0029	0.074
230	63	0.0024	0.063
270	53	0.0021	0.053
325	44	0.0017	0.044
400	37	0.0015	0.037